

**SSANCE AUTO CARE, INC.**

1100 W. CHATHAM ST.

CARY, NC 27511

(919) 461-0700

Repair Order # 0050777

Date : 8/25/2025

Page 1 of 1

Center : 1

Customer : HALLBERG, SIMON Address : City : CARY, NC 27511- Phone 1 : ( 336 ) 831-5800      Ext : Phone 2 : ( 919 ) -                      Ext :	Vehicle : 2011 LEXU LX570 License : 55D-YAR                      Clr : SLV VIN : JTJHY7AXXB4068718 Fleet #: Engine : 5.7L                              Trans : AUTO Mileage : 205668                          Dr : 5
--	---

Parts				Labor					
Quan	Part Number	Description	Price	Op	Tech	Description	Time	Charge	
1.00	DLTOP37A	ENGINE OIL PAN	189.50	0	15	CK NO OIL IN CAR *DO NOT START		0.00	
7.00	MISC	BODY PANEL PUSH PIN	21.00	CC	001 15	DIAG AND REPLACE LEAKING REAR MAIN		2500.00	
1.00	8PK-2410	DRIVE BELT	83.32			ENGINE			
1.00	89502	ACC IDLER PULLEY	121.68			SEAL			
1.00	16031-0S010	THERMOSTAT ASSY	64.52						
1.00	16326-38010	T-STAT GASKET	7.10						
1.00	MS19736	INTAKE MANIFOLD GAS	27.33						
1.00	CD010419	AC CONDENSER	312.60						
3.00	FR/134A	134A REFRIGERANT	116.67						
1.00	BG-702	FRIGI A/C OIL / DYE	13.68						
3.00	AF/1	ANTI-FREEZE	116.91						
9.00	MO/07 51 0 017 866	MB & BMW SYN. 5W-30	83.16						
1.00	04152-YZZA4	OIL FILTER	13.48						
3.00	ATF/D	BG TRANS FLUID SYN	75.78						
1.00	90311-A0002	CRANKSHAFT SEAL REA	51.46						
-----									
Payments:									
VISA/M, on 08/25/25			34249.83						

OK Bad	Recommendation	OK Bad	Recommendation	OK Bad	Recommendation
--------	----------------	--------	----------------	--------	----------------

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

Labor :	\$2,500.00
Parts :	\$1,298.19
Sublet :	\$0.00
Other Fees :	\$0.00
Enviro :	\$40.00
Subtotal :	\$3,838.19
Sales Tax :	\$287.86
Credit Card Fee :	\$123.78
Paid By :	Total : \$4,126.05
VISA/MC	
Pay Ref :	Paid : \$4,249.83
	Due : \$0.00

X

ANCE AUTO CARE, INC.  
 00 W. CHATHAM ST.  
 CARY, NC 27511  
 (919) 461-0700

Repair Order # 0053038  
 Date : 12/4/2025  
 Page 1 of 1  
 Center : 1

Customer : HALLBERG, SIMON  
 Address :  
 City : CARY, NC 27511-  
 Phone 1 : ( 336 ) 831-5800  
 Phone 2 : ( 919 ) 607-9890

Vehicle : 2011 LEXU LX570  
 License : 55D-YAR  
 VIN : JTJHY7AXXB4068718  
 Fleet #:  
 Engine : 5.7L  
 Mileage : 210200

Clr : SLV  
 Trans : AUTO  
 Dr : 5

Parts

Labor

Quan	Part Number	Description	Price
1.00	04152-YZZA4	OIL FILTER	13.48
8.00	MO 5W30	CASTROL BULK	62.48
1.00	WS/1	WASHER SOLVENT	4.13
1.00	SR	SEAL RING	3.65

Op	Tech	Description	Time	Charge
0	4	MINOR		0.00
		GEN CK		
		CK TPMS LIGHT ON		
		**CALL DEBBIE		25.00
PM 001	4	MINOR SERVICE- CHANGE OIL AND FILTER, CK ALL FLUID LEVELS, SET TIRE PRESSURE, CK ALL LIGHTS, CK BELTS & HOSES, CK BRAKES, GENERAL CK OVER OF ENTIRE VEHICLE		
CC 001	4	SLIGHT SEEP AT OIL PAN. CLEANED AND WILL MONITOR		0.00
		REAR BRAKE PADS AT 25%. WILL MONITOR AT NEXT OIL SERVICE 5K MILES		
		TPMS LIGHT RESET WILL SETTING TIRE PRESSURE. NO PROBLEM FOUND		

Payments:  
 VISA/M, on 12/04/25 \$123.68

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
✓		ALIGNMENT	✓		BELTS & HOSES	✓		OTHER
✓		TIRES	✓		EXHAUST	✓		CHARGING SYS
✓		ELECTRICAL	✓		ENGINE	✓		TRANSMISSION
✓		DRIVE TRAIN	✓		BRAKES	✓		SUSPENSION
✓		STEERING	✓		COOLING SYS	✓		HEATING & A/C
✓		LIGHTS	✓		* SERVICE DUE	✓		OTHER
					30K MAJOR			OK

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

Labor :	\$25.00
Parts :	\$83.74
Sublet :	\$0.00
Other Fees :	\$0.00
Enviro :	\$7.61
Subtotal :	\$116.35
Sales Tax :	\$3.73
Credit Card Fee :	\$3.60
Paid By :	Total : \$120.08
VISA/MC	
Pay Ref :	Paid : \$123.68
	Due : \$0.00

# *Renaissance*

**AUTO CARE INC.**

---

*Specializing in Mercedes Benz, BMW,  
Honda & Acura*

---

**JAY PARRISH**  
**919/461-0700**

**1100 W. Chatham St.**  
**Cary, N.C. 27511**

**[Reny4@mindspring.com](mailto:Reny4@mindspring.com)**